


Fall Protection


TWIN NANO-LOK EDGE

Shock Pack Cover Replacement Procedure

SUPPLEMENTAL INSTRUCTION 5908483 Rev. B











1.0 SHOCK PACK COVER REMOVAL

After inspecting the Self Retracting Device (SRD) per its user instruction manual, perform the following steps if a new shock pack cover is required. The rest of the SRD must pass inspection before this procedure. See Figure 1 for reference:

- 1. Obtain a thin ruler or similarly-shaped object to use for removal of the shock pack cover. The object should be thin and flat, and neither end of the object should be sharp. Do not use scissors for removal of the shock pack cover.
- 2. Mark your ruler or other, similar tool 2.5" from one end.
- 3. Place the shock pack upon a flat surface. Place it so that its back side is facing up (the side without the labels).
- 4. Insert the end of the tool from Steps 1 and 2 between the two layers of webbing at the location shown (see Figure 4A). Slide the tool into the shock pack until it reaches the line marked at 2.5" (4B).
- 5. Slide the tool within the shock pack; first, all the way to the left, then all the way to the right. This should help to detach the black hook and loop materials within the shock pack.
- 6. With the tool still in place, grab the web strap (6A) of the shock pack and gently guide it out of the shock pack cover's opening (6B).
- 7. Pull end of the web strap (7A) under the round bar (7B) of the interface.
- 8. With the shock pack cover now loose, alternately pull on each leg of the shock pack cover until it comes off the internal energy absorber.
- 9. With the shock pack cover removed, perform the following inspection of the internal energy absorber:

Component:	Inspection:	User	Competent Person
Internal Energy Absorbers (Figure 9.9)	Verify that the tear web (B) is not damaged and that it is contained within the two shrink tube pieces (A).		
	Ensure that the stitch pattern (E) is not damaged.		
	Confirm that the black plastic collar (C) and the rivet (D) are intact and not damaged.		

[☑] Dispose of the Nano-Lok Edge SRD if it has been subjected to fall arrest forces or if inspection reveals an unsafe or defective condition. Before disposing of the SRD, cut the cable lifeline in half or otherwise disable the SRD to eliminate the possibility of inadvertent use.

2.0 NEW SHOCK PACK COVER INSTALLATION

After removing an old shock pack cover through the procedure detailed in Section 1 ("Removal"), perform the following steps if a new shock pack cover needs to be installed. The rest of the SRD must pass inspection before this procedure, in addition to the internal energy absorbers inspection (see Section 1, Step 9). See Figure 2 for reference:

- 1. Place the new shock pack cover on a flat surface (see Figure 1A). Place it with its logo side down, alongside the SRD assembly, which should be placed with the buttons of its interface facing down (1B).
- 2. Open the end of the shock pack cover and insert the ends of the internal energy absorbers into the sleeve of the cover (2A). Pull the shock pack cover over the internal energy absorbers, feeding the two legs of the energy absorbers into separate pockets of the shock pack cover (2B).
- 3. Once the shock pack cover is pulled up to the mouth of the interface (3A), bring the web strap back into the sleeve of the shock pack cover. First, slide the web strap (3B) under the round bar of the interface (3C).
- 4. Insert the tool from Section 1 into the pocket on the end of the web strap.
- 5. With the tool still in the pocket of the web strap, guide the web strap and the tool inside the sleeve of the shock pack cover.
- 6. Continue to push the tool and web strap into the shock pack cover until the tool reaches the 2.5" line marked in Section 1, Step 2. The web strap should now be fully inserted within the shock pack cover.
- 7. Remove the tool from within the shock pack cover, keeping the web strap inside. Press the material now above the web strap down firmly, so that the hook and loop material locks the web strap into place.
- 8. Flip the SRD unit over and verify that the internal energy absorber is fully concealed by the new shock pack cover. The shock pack cover logo and the connector buttons of the interface should both be facing the same direction.

3.0 APPLICATION

The procedures covered in this supplemental instruction apply to the following Twin Nano-Lok Edge models only:

3500225	3500227	3500229	3500231	3500249	3500263
3500226	3500228	3500230	3500246	3500257	3500271





Fall Protection

USA

3833 SALA Way Red Wing, MN 55066-5005 Toll Free: 800.328.6146 Phone: 651.388.8282 Fax: 651.388.5065 3Mfallprotection@mmm.com

Brazil

Rua Anne Frank, 2621 Boqueirão Curitiba PR 81650-020 Brazil

Phone: 0800-942-2300 falecoma3m@mmm.com

Mexico

Calle Norte 35, 895-E Col. Industrial Vallejo C.P. 02300 Azcapotzalco Mexico D.F. Phone: (55) 57194820 3msaludocupacional@mmm.com

Colombia

Compañía Latinoamericana de Seguridad S.A.S. Carrera 106 #15-25 Interior 105 Manzana 15 Zona Franca - Bogotá, Colombia

Phone: 57 1 6014777 fallprotection-co@mmm.com

Canada

260 Export Boulevard Mississauga, ON L5S 1Y9 Phone: 905.795.9333 Toll-Free: 800.387.7484 Fax: 888.387.7484 3Mfallprotection-ca@mmm.com

EMEA (Europe, Middle East, Africa)

EMEA Headquarters: Le Broc Center Z.I. 1re Avenue - BP15 06511 Carros Le Broc Cedex France

Phone: + 33 04 97 10 00 10 Fax: + 33 04 93 08 79 70 information fall protection @mmm.com

Australia & New Zealand

137 McCredie Road Guildford Sydney NSW 2161 Australia

Phone: +(61) 2 8753 7600 Toll-Free: 1800 245 002 (AUS) Toll-Free: 0800 212 505 (NZ) Fax: +(61) 2 8753 7603

anzfallprotectionsales@mmm.com

Asia

Singapore: 1 Yishun Avenue 7 Singapore 768923 Phone: +65-6450 8888 Fax: +65-6552 2113 TotalFallProtection@mmm.com

China:

38/F, Maxdo Center, 8 Xing Yi Rd Shanghai 200336, P R China Phone: +86 21 62753535 Fax: +86 21 52906521 3MFallProtecton-CN@mmm.com

Korea:

3M Koread Ltd 20F, 82, Uisadang-daero, Yeongdeungpo-gu, Seoul Phone: +82-80-033-4114 Fax: +82-2-3771-4271 TotalFallProtection@mmm.com

Japan: 3M Japan Ltd

6-7-29, Kitashinagawa, Shinagawa-ku, Tokyo Phone: +81-570-011-321

Fax: +81-3-6409-5818 psd.jp@mmm.com

WEBSITE: 3M.com/FallProtection





EU DECLARATION OF CONFORMITY: 3M.com/FallProtection/DOC